APPENDIX V

Comments to Corbin's second Wayfinding Plan

## Comments to the Exterior Wayfinding Sign Package presented by Corbin on November 20, 2002

## **General Comments**

- The preliminary design illustration identified the logo at the top of the post with a triangular design. We would like some notes on its assembly, as well as, dimensions. We are concerned about the structure and longevity of this design and request that the design be modified to reflect a single flat panel. We would also like to see drawings and dimensions that would accompany this design change that would reflect a single flat panel, in place of the proposed triangular structure. Please also clarify if the size of these, in both cases, will vary depending on the size of the panels with the sign copy (large 5' panels or small 4' panels).
- The current drawings show the signs mounted or attached using a plate and bolting system. We would prefer to have the pole buried at a depth of three or four feet and request that the final design illustrate this method of installation.
- We request a set of engineering drawings for the signs.
- We request dimensions for the parking sign, which will be at the corner of Paul Laurence Dunbar Street and Edison (see sign 1P in plan).

**Specific Comments** 

<u>opcomo oo</u>	Specific Confinents					
Sign No.	Preliminary Comments to Wayfinding Plan as of January 16, 2003					
1	No comment					
	General Comments:					
	Specific Text Comments: Directional arrows for parking should					
1P	indicate turn right.					
2	No comment					
3	No comment					
<b>4</b>	No comment					
5	No comment					
6	No comment					
	General Comments:					
	Specific Text Comments: Add to sign copy U.S. Air Force Museum.					
7	Directional arrow should indicate straight ahead.					
	General Comments:					
	Specific Text Comments: Replace National Aviation Hall of Fame with					
	Dunbar House State Memorial. Directional arrow should indicate turn					
8	left.					
9	No comment					
10	No comment					
11	No comment					
12	No comment					
	General Comments: Based on photo, sign face direction is north.					
	Specific Text Comments: Sign should therefore read Wright Brothers					
13	Aviation Center. Directional arrow should indicate turn right.					

ļ		General Comments: Based on photo, sign face direction is west.	
]		Specific Text Comments: Sign should therefore read Wright Cycle Co.	
		/ National Aviation Hall of Fame / U.S. Air Force Museum. Directional	
ļ	14	arrow should indicate turn left.	
		General Comments:	
1	15	Specific Text Comments: Directional arrow should indicate turn left.	
l. [	16	No comment	
	17	No comment	•
ĺ	18	No comment	
		General Comments:	
		Specific Text Comments: Sign should read Wright Bros. / Dunbar.	
[	19	Directional arrow should indicate veer left.	
. [		General Comments:	
		Specific Text Comments: Sign should read Wright Cycle Co. / Wright -	Ī
1		Dunbar Visitor Center / Dunbar House State Memorial. Directional arrow	Ī
	20	should indicate turn right.	
i		General Comments:	
		Specific Text Comments: Sign should read Wright Bros / Dunbar.	
ļ	21	Directional arrow should indicate turn left.	
	22	No comment	
	23	No comment	
		General Comments: Photo for this sign is incorrect, there is no photo	
		available.	
		Specific Text Comments: Order of text should read Wright Brothers	
	24	Aviation Center / Dunbar House State Memorial / Wright Cycle Co.	
l	.,	General Comments: Picture associated with this sign is photo 24.	
		Specific Text Comments: Order of text should read Wright Brothers	
	24a	Aviation Center / Dunbar House State Memorial / Wright Cycle Co.	,
		General Comments: This sign falls within the jurisdiction of ODOT	estate per per productiva de la constante de l La constante de la constante d
Service of the servic	Editor (Editorial Marie Marie Editorial Section (1997) (19	District 8 and they will oversee the sign design. For the purpose of the	Militar i da di Hiritari di Palanda Santari
		plan, the sign design has to comply with ODOT standards and note that	-
	25	design, fabrication, and installation will be by ODOT.	
		General Comments:	
<u>l</u>		Specific Text Comments: Replace Wright Brothers Aviation Center	
ļ	26	with Wright Brothers Sites.	
		General Comments:	•
		Specific Text Comments: Replace Wright Brothers Aviation Center	
	27	with Wright Brothers Sites. Directional arrows should indicate <i>veer right</i> .	
į		General Comments:	
		Specific Text Comments: Replace Wright Brothers Aviation Center	
		with Wright Brothers Sites. Directional arrows for all sites should	
	28	indicate turn right.	
		General Comments:	
		Specific Text Comments: Sign should read Dunbar House State	
ļ	28a .	Memorial / Wright Cycle Co. Directional arrows should indicate turn <i>left</i> .	
	29	General Comments: Photo in document is incorrect.	
- ' '		General Comments. I floto in document is moon cot.	

		· · · · · · · · · · · · · · · · · · ·
		Specific Comments: Directional arrows should indicate straight ahead.
	30	No comment
		General Comments: This sign falls within the jurisdiction of ODOT
		District 8 and they will oversee the sign design. For the purpose of the
		plan, the sign design has to comply with ODOT standards and note that
	31	design, fabrication, and installation will be by ODOT.
		General Comments: This sign falls within the jurisdiction of ODOT
		District 8 and they will oversee the sign design. For the purpose of the
		plan, the sign design has to comply with ODOT standards and note that
	32	design, fabrication, and installation will be by ODOT.
		General Comments: This sign falls within the jurisdiction of ODOT
	,	District 8 and they will oversee the sign design. For the purpose of the
·		plan, the sign design has to comply with ODOT standards and note that
	33	design, fabrication, and installation will be by ODOT.
		General Comments:
		Specific Text Comments: Sign should read Huffman Prairie Flying
		Field with directional arrow indicating right turn. Sign should also read
	34	Wright Cycle Co. Directional arrow should indicate turn left.
		General Comments: Based on photo sign face direction is north.
		Specific Text Comments: Sign should read Huffman Prairie Flying
		Field Visitor Center / Wright Memorial. Directional arrow should indicate
	35	turn right.
		General Comments: This sign falls within the jurisdiction of ODOT
		District 8 and they will oversee the sign design. For the purpose of the
		plan, the sign design has to comply with ODOT standards and note that
	36	design, fabrication, and installation will be by ODOT.
		General Comments: This sign falls within the jurisdiction of ODOT
	·	District 8 and they will oversee the sign design. For the purpose of the
Akas ami'n delamista asak siri tah Kitasas sisi fisikandan eng	The result of the state of the	plan, the sign design has to comply with ODOT standards and note that
na managana ang mang mga baga ng mang ang m Managana ang mang mga mga mga mga mga mga mga mga mga mg		design, fabrication, and installation will be by ODOT.

## Mileage for selected signs

	Sign Copy	Mileage
Sign 7	Wright Brothers Aviation Center	3
	U.S. Air Force Museum	5
Sign 8	U.S. Air Force Museum	5
Sign 12	Wright Cycle Co	2
	National Aviation Hall of Fame	6
	U.S. Air Force Museum	6
Sign 14	National Aviation Hall of Fame	6
	Wright Cycle Co	3
	U.S. Air Force Museum	6
Sign 17	Huffman Prairie Flying Field Visitor Center	. 7
	National Aviation Hall of Fame	6
	U.S. Air Force Museum	6 3
Sign 18	Wright Brothers Aviation Center	3
	Dunbar House State Memorial	2
	Wright Cycle Co	2
Sign 22	National Aviation Hall of Fame	3
	U.S. Air Force Museum	3
Sign 24	Dunbar House State Memorial	3
	Wright Brothers Aviation Center	4
	Wright Cycle Co	3 5 5 2 3 6 5
Sign 28a	Dunbar House State Memorial	5
	Wright Cycle Co	5
Sign 29	Huffman Prairie Flying Field Visitor Center	2
	Huffman Prairie Flying Field	3
Sign 30	Wright Brothers Aviation Center	6
	Wright Cycle Co	5
	Huffman Prairie Flying Field Visitor Center	2
Sign 34	Huffman Prairie Flying Field	2 2
	Wright Cycle Co	8